

Test Report

號碼(No.): ETR22C05972 日期(Date): 07-Jan-2023 頁數(Page): 1 of 4

台灣減摩股份有限公司 (TAIWAN GENMA CO., LTD.) 新北市新莊區五工三路78巷25號1樓 (1F, NO. 25, LANE 78, WUGONG 3RD., SINJHUANG DISTRICT, NEW TAIPEI CITY, TAIWAN)

以下測試樣品係由申請廠商所提供及確認 (The following sample(s) was/were submitted and identified by the applicant as):

送樣廠商(Sample Submitted By)

: 台灣減摩股份有限公司 (TAIWAN GENMA CO., LTD.)

樣品名稱(Sample Name)

SOLDER PASTE

樣品型號(Style/Item No.) : NP3

NP303-LHGQ-9KR, NP303-COSMO-LH-T4, PW231-LH-GQ,

WIN-DOT B-005 NP303, WINDOT F-005 NP303, NP303-COSMO-LH-T5,

NP303-COSMO-LH-T5-2, SB6-HLGO-20, SB58-COSMO-NH-T4,

FLUX-GM776

收件日(Sample Receiving Date)

30-Dec-2022

測試期間(Testing Period)

: 30-Dec-2022 to 07-Jan-2023

測試需求(Test Requested)

依據客戶指定,測試鹵素-氟、氯、溴、碘。 (As specified by client, to test Halogen-Fluorine, Chlorine, Bromine, Iodine in the submitted sample.)

測試結果(Test Results)

請參閱下一頁 (Please refer to following pages).





PIN CODF: 74BC8BA



Test Report

號碼(No.): ETR22C05972 日期(Date): 07-Jan-2023 頁數(Page): 2 of 4

台灣減摩股份有限公司 (TAIWAN GENMA CO., LTD.) 新北市新莊區五工三路78巷25號1樓 (1F, NO. 25, LANE 78, WUGONG 3RD., SINJHUANG DISTRICT, NEW TAIPEI CITY, TAIWAN)

測試部位敘述 (Test Part Description)

No.1 : 灰色膏狀 (GRAY PASTE)

測試結果 (Test Results)

測試項目	測試方法	單位	MDL	結果
(Test Items)	(Method)	(Unit)		(Result)
				No.1
氟 (F) (Fluorine (F)) (CAS No.: 14762-	參考BS EN 14582: 2016 · 以離子層析儀分析。	mg/kg	50	n.d.
94-8)	(With reference to BS EN 14582: 2016, analysis			
	was performed by IC.)			
氯 (CI) (Chlorine (CI)) (CAS No.:	參考BS EN 14582: 2016·以離子層析儀分析。	mg/kg	50	n.d.
22537-15-1)	(With reference to BS EN 14582: 2016, analysis			
	was performed by IC.)			
溴 (Br) (Bromine (Br)) (CAS No.:	參考BS EN 14582: 2016 · 以離子層析儀分析。	mg/kg	50	n.d.
10097-32-2)	(With reference to BS EN 14582: 2016, analysis			
	was performed by IC.)			
碘 (I) (Iodine (I)) (CAS No.: 14362-44-	參考BS EN 14582: 2016·以離子層析儀分析。	mg/kg	50	n.d.
8)	(With reference to BS EN 14582: 2016, analysis			
	was performed by IC.)			

備註(Note):

- 1. mg/kg = ppm; 0.1wt% = 0.1% = 1000ppm
- 2. MDL = Method Detection Limit (方法偵測極限值)
- 3. n.d. = Not Detected (未檢出); 小於MDL / Less than MDL




Test Report

號碼(No.): ETR22C05972 日期(Date): 07-Jan-2023 頁數(Page): 3 of 4

台灣減摩股份有限公司 (TAIWAN GENMA CO., LTD.) 新北市新莊區五工三路78巷25號1樓 (1F, NO. 25, LANE 78, WUGONG 3RD., SINJHUANG DISTRICT, NEW TAIPEI CITY, TAIWAN)

鹵素分析流程圖 / Analytical flow chart - Halogen





Test Report

號碼(No.): ETR22C05972 日期(Date): 07-Jan-2023 頁數(Page): 4 of 4

台灣減摩股份有限公司 (TAIWAN GENMA CO., LTD.) 新北市新莊區五工三路78巷25號1樓 (1F, NO. 25, LANE 78, WUGONG 3RD., SINJHUANG DISTRICT, NEW TAIPEI CITY, TAIWAN)

* 照片中如有箭頭標示,則表示為實際檢測之樣品/部位. * (The tested sample / part is marked by an arrow if it's shown on the photo.)

ETR22C05972



** 報告結尾 (End of Report) **